

## plugin **794**

**WARNING :** for a correct identification of the ECU it is necessary to open the ECU and always check that the ECU numbers printed on the motherboard are the same as the numbers declared on the manual. Do not trust the numbers on the ECU cover.








#### DIRECT CONNECTION


For the connection use the cable F32GN037C connected to the ECU.

Make sure that the POWER led (red) on Trasdata is ON.

These connections are required for all the connection approaches: loose wires, soldering adapter, DIMA adapter.



# ECU CONNECTOR




#### LOOSE WIRES CONNECTION:

For the READING and WRITING procedure use the FLAT cable F34NTF53


	1 25 2 26	
Pin	Colore Colour	
11	Non usato	
2010/00	Not used Non usato	
1.2	Not used	
13	Non usato	
	Not used Non usato	
14	Not used	
15	Verde	
	Green Blu	
16	Blue	
17	Viola	
17	Violet	
18	Grigio Grey	
10	Bianco	
19	White	
20	Nero	
	Black	
21	Marrone	
	Brown	
2.2	Rosso Red	
	Arancio	
23	Orange	
24	Giallo Yellow	
	Verde	
25	Green	
26	Non usato Not used	

**WARNING**: for a correct reading and writing operation it is necessary to perform a LINK between the pads displayed in the picture here below. Remove the LINK before placing back the ECU into the car.




# F34NTA17 Soldering adapter connection or F34DM024 DIMA adapter connection.

In both cases, for a correct connection, it is necessary to identify the pin 1 for the reading&writing procedures and the pin 18 to enable the Microprocessor communication.




#### F34NTA17 Soldering adapter connection






By using the grey wire supplied with the adapter connect the pad 18 (see pg.6) to the specific connector on the adapter itself.

The following picture of the F34NTA17 adapter connection is merely indicative.



#### F34DM024 DIMA adapter connection





By using a wire connect the pad 18 (see pg.6) to the specific orange clamp ENA present on the F34DM024 DIMA adapter.

The following picture of the F34DM024 DIMA adapter connection is merely indicative.

