plugin **512**

With this plugin it is NOT possible any Microprocessor reading or ECU clone operation. On this ECU it is possible only the PATCH UNLOCK, operation required to perform the serial writing with the New Genius protocol FLASH 0396.

To perform the PATCH UNLOCK you can follow the instructions at pag. 5 of this manual.





ECU CONNECTOR

In order to connect to the ECU use the CABLE F32GN037C. Make sure that the POWER led (red) on Trasdata is ON.

COLORE FILO WIRE COLOUR		DESCRIZIONE DESCRIPTION		
ROS	550)	POSITIVO DIRETTO POWER BATTERY		
ARA ORA	ANCIO ANGE	POSITIVO SOTTO QUADRO POWER SWITCH ON		
NER	RO ACK	MASSA GND		
GIA YEL	LLO LOW	KLINE		
VER	RDE EEN	CAN LOW		
BIA	NCO ITE	CAN HIGH		
GRI	IGIO EY	POL4 BOOT	F32GH037C	
BLU BLU	J JE	POL5 CNF1		
VIO PUR	DLA/GRIGIO RPLE/GREY	TENSIONE PROG. PROG. VOLTAGE	CHANNES .	
MAR BRC	RRONE DWN	RESET		



BOOT & CNF1 DIRECT CONNECTION

Connect the BLUE and GREY wirings of the F32GN037C cable as shown here below:

COL	ORE FILO E COLOUR	DESCRIZIONE DESCRIPTION	
	GRIGIO GREY	POL4 BOOT	
	BLU BLUE	POL5 CNF1	



PATCH UNLOCK

To unlock the ECU and then proceed with the serial OBDII programming procedure with FLASH 0396 it is necessary to follow these instructions:

- Connect the ECU to the Trasdata as described in the previous pages
- Select the correct connection mode or vehicle.
- Perform the identification of the ECU clicking on the "ID" button.
- After the correct identification select the ECU option then proceed with the reading by clicking on "READ" button. At the end of the reading save the file .DIM on the pc.

	OPERATIONS	
*	C ECU	READ
<u> </u>	C Ext. Flash	S WRITE
*	C TUNING FILE	PATCH
•		
•	Notes	
Info Plugins		
ine ringine		

• After saving the ECU .DIM file leave the option ECU selected and click on "PATCH" button.

The software, in order to run the patch, will ask for the .DIM file read just before. Select the .DIM file and the Trasdata will execute the unlock of the ECU.

	OPERATIONS
▼ ▼ ▼	Image: Constraint of the second se
▼ ▼ Info Plugins	Notes PATCH UNLOCK: necessary patch to unlock OBD2 programming of modified file