
plugin 1082





ECU CONNECTOR


In order to connect to the ECU use the cable F32GN037C/D.

Make sure that the POWER led (red) on Trasdata is ON.

These connections are required for all the connection approaches: loose wires and metal positioning frame adapter.


COLORE FILO WIRE COLOUR		DESCRIZIONE DESCRIPTION	
RC RE	OSSO ED	POSITIVO DIRETTO POWER BATTERY	
200	RANCIO RANGE	POSITIVO SOTTO QUADRO POWER SWITCH ON	
1000	ERO LACK	MASSA GND	
1073	ALLO ELLOW	KLINE	
800	ERDE REEN	CAN LOW	
10000	ANCO HITE	ICAN HIGH	9
	RIGIO REY	POL4 BOOT	6
BL BL	.UE	POL5 CNF1	
1000		TENSIONE PROG. PROG. VOLTAGE	-
10000	ARRONE ROWN	RESET	






J-TAG LOOSE WIRES CONNECTION


For the reading & writing procedures use the FLAT cable F34NTF53




Connect the wires on the pads avoiding any short circuits.




Connect the wire 23 as descrive in the following pictures.







METAL POSITIONING FRAME CONNECTION


For the metal positioning frame connection are required the F34DM036 +F34DM038 adapters, JTAG pads for the communication are placed below the microprocessor.







Set up the base adapter F32DM036 with the F34DM037 adapter as displayed in the following picture.



Verify the PIN 1 location and connect the pin WDS to the corresponding clamp on the base adapter F34DM036 as in displayed in the following picture.

Place F34DM036+F34DM038 adapters as displayed in the following picture.

